


Corrosion Detection/Burnout Indication



TC junctions start to break down before burnout - an increase in the junction resistance can be an early indication of TC degradation or pending failure