

Temperature Transmitters and Assemblies

T10: Temperature Calibration Made Easier

Problem: Precise temperature calibration is time consuming. Is there a better alternative?

Solution: Hook up your sensor or calibrator to the TDY PC-Programmable Temperature Transmitter with Display. The point and click software enables immediate capture of two points within your desired range thus input calibrating the transmitter. This method produces an extremely accurate measurement in just seconds.



Model Number Example

TDY / PRG / 4-20MA / 12-42DC [BH2NG]