


G-type DIN-Rail Adapter Kit



Be sure to visit us at www.miinet.com/DINRailAdapter where you can also find a instructional video on how to properly assemble and install this adapter.

View 2 (Front View) Proceed to slide/adjust adapter assembly to required location and tighten the middle screw to secure in place as shown in View -1. Once secured, center your Moore Industies' Instrument in place correctly as shown in View 2, and snap onto adapter assembly as shown in

Instrument Latch

(1)

View 3 (Side View)

G-Rail

 $(\mathfrak{U}$

View 1 (Front View)

Views 2 and 3.

(2)